



EXPERIENCE REQUIREMENTS FOR ASBESTOS CERTIFICATION

	Worker	Site Supervisor	Inspector	Management Planner	Project Designer
Work Experience	At least 1000 hours of work experience in general commercial construction trades; OR	At least 2000 hours of work experience in asbestos-related work, safety, industrial hygiene, hazardous materials control, or other general commercial construction trades; OR	Work experience of at least 500 hours in the field of building inspection, asbestos-related work, safety, industrial hygiene, or hazardous materials control; OR	Work experience of at least 1000 hours in the field of building inspection, asbestos-related work, safety, industrial hygiene, or hazardous materials control; OR	Work experience of at least 4000 hours in asbestos-related work or asbestos management activity; OR
Work Experience and/or Secondary Degree	Two years of postsecondary education with an emphasis in construction management, industrial hygiene, industrial technology safety, or physical or life science, AND completed an Occupational Safety and Health Administration's (OSHA) 510 Occupational Safety and Health Standards for the Construction Industry course; OR	1. Bachelor degree in architecture, engineering, physical or life science AND at least 500 hours of work experience in asbestos-related work, safety, industrial hygiene, hazardous materials control or other general commercial construction trades; OR 2. Master's degree in environmental health, industrial hygiene or safety; OR	Bachelor degree in architecture, engineering, industrial hygiene, industrial technology safety, or physical or life science AND 40 hours of on-site asbestos inspection experience accompanying a Minnesota certified asbestos inspector; OR	1. Bachelor degree in architecture, engineering, physical or life science AND at least 500 hours of work experience in the field of building inspection, asbestos-related work, safety, industrial hygiene, or hazardous materials control; OR 2. Master's degree in environmental health, industrial hygiene or safety AND at least 250 hours of work experience in the field of building inspection, asbestos-related work, safety, industrial hygiene, or hazardous materials control; OR	
Vocational/ Technical Training	Completion of a Vocational/Technical Training Program in a construction-related discipline of at least 18-months; OR				
Apprenticeship	At least two years full-time attendance at an apprenticeship program for general commercial construction trades.	Completion of an apprenticeship program within the general commercial construction trades.	Completion of an apprenticeship program within the general commercial construction trades; OR		
Professional Licensure, Registration or Certification			1. Licensure by Minnesota as a building official; OR 2. Registered, licensed or certified as an architect, PE, CIH or CSP.	1. Licensure by Minnesota as a building official; OR 2. Registered, licensed or certified as an architect, PE, CIH or CSP.	Registered, licensed or certified as an architect, PE, CIH or CSP.